ECAS v 1.0 - Microsoft Internet Explorer

ACE Team

Applied Cost Engineering

Specify Task
Design Attributes
Characterization
Site Type
Site Work
Enter WBS
X-CHOOSE-X
Sample, Monitor, and Analysis
Disposal Methods
Subcontracting Strategy
Copy
Exit

Specify Task

This is the PBS Number for the Task as Specified with the task.

NON-QA

OPS Office:	TST	Task:	1000	Phase:	04	Site Location:	Anytown, PA

Operations Office: TEST OPERATIONS

Site Location: Anytown, PA [Comment]

Program: ENVIRONMENTAL RESTORATION

Task #: 1000 Test 1 [Comment]

Phase ID: 4 (Remedial Action) [Comment]

Task Start Date: 04-MAR-1991 [Comment]

Task End Date: 30-MAY-1993 [Comment]

Centroid Date: 01-FEB-1992 [Comment]

Total Quantity: 1 **UOM** X-CHOOSE ONE-X

Total Cost: 100000

Phase Start Date: Month: APR Year: 1991 [Comment]

Phase End Date: Month: APR Year: 1993 [Comment]

Phase Type UOM: **ENGLISH:** ◉ **METRIC:** ○

PBS #: SR-ER01 [Comment]

Prime Contract Type: Cost + Award Fee [Comment]

Prime Contract Dates: 01-OCT-1993 - 30-SEP-1995 [Comment]

Quantity Status: *Estimate:* ○ *Actual:* ◉

Type Cost: *Burdened:* ◉ (Overhead Rate) 0 % *UnBurdened:* ○

[Add Reference Tasks]

Safety Protection Level:

Level A	Level B	Level C	Level D	Level E
0 %	0 %	20 %	50 %	30 %

[Submit]